



**BARNHILL
CONTRACTING
COMPANY**

2311 North Main Street
PO Box 1529
Tarboro, North Carolina 27886
252-823-1021 Fax: 252-823-0137

www.barnhillcontracting.com

July 28, 2011

Mr. Ben Barnes
Environmental Senior Specialist
PO Box 8998
Rocky Mount, North Carolina 27804

Re: LCID Annual Report
Permit #33-F

Dear Mr. Barnes,

Please find enclosed the annual report for Barnhill Contracting Company's Land Clearing and Inert Debris Landfill. This facility annual report is for the Rocky Mount Asphalt Plant LCID, permit #33-F. I have also sent a copy of this report to the County Manager of each county from which waste was received.

Should you require any additional information, please do not hesitate to contact us.

Yours very truly,
Barnhill Contracting Co.

Jonathan Proctor
Estimator

Enclosure



According to (G.S. 130A-309.09D(b)) completed forms must be returned by August 1, 2011 and a copy of this report must be sent to the County Manager of each county from which waste was received. If you have questions or require assistance in completing this report, contact your Regional Environmental Senior Specialist.

Facility Name: Barnhill Contracting LCID Landfill Permit: 33F-LCID- ID: P1017

Facility Website (URL): _____

Physical Address		Mailing Address	
Street 1: <u>10826 HWY 97</u>		Street 1: <u>PO Box 1529</u>	
Street 2: _____		Street 2: _____	
City: <u>Rocky Mount</u>	County: <u>Edgecombe</u>	City: <u>Tarboro</u>	
State: <u>North Carolina</u>	Zip: <u>27801</u>	State: <u>North Carolina</u>	Zip: <u>27886</u>

Primary Facility Contact Person		Billing Contact Person	
Name: <u>Buddy Rose</u>		Name: <u>Jonathan Proctor</u>	
Phone: <u>(252) 813-6200</u>	Fax: <u>(252) 823-0137</u>	Phone: <u>(252) 824-8287</u>	Fax: <u>(252) 823-0137</u>
Email: <u>brose@barnhillcontracting.com</u>		Email: <u>jproctor@barnhillcontracting.com</u>	

1. Tipping Fee: \$ _____ per N/A
Tipping Fee: \$ _____ per N/A
Tipping Fee: \$ _____ per N/A

2. Estimate the amount of waste taken in an average week at this facility? 120 ☐ tons
☒ cubic yards

3. How many weeks did you operate this year? 40

4. What are the hours/days of operation for this facility? 6:30 AM to 6:30PM Monday thru Saturday

5. What is the acreage of the footprint of the waste on site as of June 30? 10.66 Acre(s)

6. Did your facility stop receiving waste during this past Fiscal Year? ☐ Yes ☒ No

If so, please report the date this occurred: _____

REMINDER: According to (G.S. 130A-309.09D(b)), this report must be sent to the Regional Environmental Senior Specialist for your area and a copy of this report must be sent to the County Manager of each county from which waste was received.

Please return your completed report to:

Ben Barnes
PO Box 8998
Rocky Mount, NC 27804-6998
phone: 252.459.4502 email: Ben.Barnes@ncdenr.gov

CERTIFICATION: I certify that the information provided is an accurate representation of the activity at this facility.

Signature:  Date: Jul 28, 2011

Name: Jonathan Proctor Title: Estimator

Phone Number: (252) 824-8287 Email: jproctor@barnhillcontracting.com

Facility Name: Barnhill Contracting LCID Landfill Permit: 33F-LCID-

Address: 10826 HWY 97

City: Rocky Mount State: North Carolina Zip: 27801

Person completing Assessment: Jonathan Proctor Date: Jul 28, 2011

Phone Number: (252) 824-8287 Fax: (252) 823-0137 Email: jproctor@barnhillcontracting.com

Instructions: Please indicate either *Yes* or *No* for each Receptor and Post Closure Maintenance question. Then please determine the distance or distances for each Receptor from the *Edge of Waste* (using range finders and/or GIS maps) and type that information into the form. Please attach additional information including GIS maps, lists of potable well locations, etc.

Receptors

1. Are there Residential Dwellings Within 1,500 feet of the Edge of Waste? ☒ Yes ☐ No
If Yes, how many? 1
What are the three closest distances from the *Edge of Waste*? ±850 Feet Feet Feet
2. Are there Potable Wells Within 1,500 feet of the Edge of Waste? ☒ Yes ☐ No
If Yes, how many? 1
What are the three closest distances from the *Edge of Waste*? ±850 Feet Feet Feet
3. Are there Community/Municipal Wells Within 1,500 feet of the Edge of Waste? ☐ Yes ☒ No
If Yes, how many?
What are the three closest distances from the *Edge of Waste*? Feet Feet Feet
4. Are there Surface Water Bodies Within 1,500 feet of the Edge of Waste? ☒ Yes ☐ No
If Yes, how many? 3
What are the three closest distances from the *Edge of Waste*? ±50 Feet ±50 Feet ±50 Feet
Please list the names of the water bodies: 3 closed out sand pits
5. Is Public Water Available Within 1,500 feet of the Edge of Waste? ☐ Yes ☒ No
If Yes, how many of the Residential Dwellings noted above are connected?

Corrective Measures

6. Is there an active methane extraction system (blower, flare, etc.)? ☐ Yes ☒ No
7. Is there a passive methane extraction system (trench, vents in cap, flare, etc.)? ☐ Yes ☒ No
8. Is there groundwater remediation taking place on site? ☐ Yes ☒ No
If Yes, what is the specific remedial technology used?

Comments

Please see attachment for location of residential dwelling with potable well within 1500' of the edge of waste. The aerial was taken from Edgecombe County's GIS website.

